## State of California The Resources Agency DEPARTMENT OF WATER RESOURCES

**DIVISION OF FLOOD MANAGEMENT** 



# 2004 PROJECT CHANNEL REPORT

INSPECTION OF FLOOD CONTROL PROJECT CHANNELS ON THE SACRAMENTO AND SAN JOAQUIN RIVERS AND THEIR TRIBUTARIES AND THE TRUCKEE RIVER

Prepared By The Flood Operations Branch Flood Project Inspection Section

### STATE OF CALIFORNIA Arnold Schwarzenegger, Governor

### THE RESOURCES AGENCY Mike Chrisman, Secretary

#### DEPARTMENT OF WATER RESOURCES Lester A. Snow, Director

### DIVISION OF FLOOD MANAGEMENT Leslie Harder Jr., Chief

### This report was prepared Under the direction of

Jay S. Punia, Chief	Flood Operations Branch				
A	and				
Richard E. Marshall, Chief Flood Project Inspection Section					
Assisted by					
Rick Burnett  Herman Phillips  Gerald Snow  Mark Soto  Clay Thomas  Richard Willoughby  Robert House	Water Resources Technician II Water Resources Technician II Water Resources Technician II Water Resources Technician II				

#### **TABLE OF CONTENTS**

	PAGE
ORGANIZATIONINTRODUCTIONCHANNEL INDEX	3
Chapter I – Inspected on the Sacramento River and Tributaries	
Ash Creek-Modoc County	6
Dry Creek-Modoc County	10
McClure Creek	14
Salt Creek	18
Big Chico Creek	
Lindo Channel and Sandy Gulch	
Little Chico Creek	34
Chapter II – Inspected on the Truckee River and the Fairfield Vicinity Streams	
Truckee River	42
McCoy Creek	46
Laurel Creek	50
Union Avenue Diversion	54
Chapter III – Inspected on the San Joaquin River and Tributaries	
Bear Creek	58
Black Rascal Creek	
Burns Creek	
Mariposa Creek	
Miles Creek	
Owens Creek	
Ash Slough	
Berenda Slough	94
Chowchilla River	
Fresno River	108
North Littlejohn Creek	112
Duck Creek Diversion	
South Littlejohn Creek	
South Littlejohn Creek, North Branch	124

#### INTRODUCTION

This is a report of the inspection of flood control project channels on the Sacramento, San Joaquin Rivers and their tributaries and the Truckee River. The inspected channels are not confined by project levees. The purpose of the inspection is to identify and report to the constructing authority and the maintaining agency any conditions, which may diminish channel capacity. In general, maintaining the channels to the condition that existed after the completion of the initial construction will preserve their flood flow characteristics. The standard of comparison for the inspection is, therefore, the condition immediately after construction.

The U.S. Army Corps of Engineers and the State of California constructed the improved channels and floodways included herein. The constructing authority issued operation and maintenance manuals to the maintaining agency. Maintaining agencies are local agencies or the State of California. These agencies agreed to be responsible for maintenance at the time of project construction or at a later time. The State conducts periodic inspections of the quality of the maintenance accomplished by the maintaining agencies, and reports its findings to these agencies. The Division of Flood Management, Flood Operations Branch, and Flood Project Inspection Section perform the inspections on behalf of The Reclamation Board.

### **CHAPTER I**

# PROJECT CHANNELS INSPECTED ON THE SACRAMENTO RIVER AND TRIBUTARIES

#### MODOC COUNTY

#### **Maintained by Adin Community Services District**


#### **ASH CREEK**

On October 22, 2004 an inspection was made of the Ash Creek Channel. Project channel limits begin at the gauging station upstream of State Highway 299 and extend downstream for 1.0 mile. The entire one-mile was inspected. The photos on the following pages are typical of, but do not show all the growth in the channel. Evidence of previously moderate to heavy erosion has occurred along both banks downstream of Ash Street. The log dam located at the downstream boundary was replaced in October 1999 with a concrete dam and fish ladder by the Department of Fish and Game. The district has an excellent maintenance program.

#### MODOC COUNTY Ash Creek



Upstream from Main street (Highway 299) towards the gauging station.



Downstream from Main street (Highway 299) looking at the Ash street water crossing.

#### MODOC COUNTY Ash Creek




Downstream from Ash street, right bank erosion and tree growth.



Downstream at a sharp left bend moderate erosion on both banks.

#### MODOC COUNTY Ash Creek



Downstream from the fish ladder and metal walkway.



Upstream from the fish ladder and metal walkway. Constructed October 1999 by the Department of Fish and Game.

### MODOC COUNTY Maintained by Adin Community Services District

#### **DRY CREEK**

On October 22, 2004 an inspection was made of the Dry Creek channel. The project channel begins at the intersection of Adin and Cedar Streets in Adin and extends downstream for 0.2 miles to its confluence with Ash Creek. The entire 0.2 miles was inspected. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show, all the growth in the channel. There is light to moderate willow growth along the entire reach of the channel.

#### MODOC COUNTY Dry Creek



Upstream where Dry Creek meets Ash Creek.



**Downstream at Cedar street.** 

#### MODOC COUNTY Dry Creek



Upstream from Main street (Highway 299), moderate growth in channel.



Downstream from Main street (Highway 299), moderate growth in channel.

#### SACRAMENTO RIVER AND TRIBUTARIES

**Maintained by Tehama County** 

#### McCLURE CREEK

On October 15, 2004, an inspection was made of the McClure Creek channel. The project channel begins 200 feet upstream of the extension of Fairfield Avenue and extends downstream 1.7 miles to 3,700 feet downstream of Road 99W. The views of the channel are from road intersections or crossings and at random distances measured from upstream of the Road 99W bridge. The photos on the following pages are typical of, but do not show, all of the growth in the channel. The channel is clear, although in some areas berry vines are beginning to encroach into the channel and bamboo is starting to take over. The channel will easily carry the required capacity. Clearing of the entire channel was completed in 1996. Satisfactory maintenance program.

### SACRAMENTO RIVER AND TRIBUTARIES McClure Creek



**Upstream at Truckee Avenue.** 




**Downstream from Truckee Avenue.** 

### SACRAMENTO RIVER AND TRIBUTARIES McClure Creek



Upstream from old Highway 99 bridge.



Downstream from old Highway 99 bridge.

#### SACRAMENTO RIVER AND TRIBUTARIES

**Maintained by Tehama County** 

#### SALT CREEK

On October 15, 2004, an inspection was made of the Salt Creek channel. The project channel begins 1.6 miles upstream of the Sacramento River and extends downstream 1.6 miles to Salt Creek's confluence with the Sacramento River. Inspection was limited to breaks in the dense vegetation, measured randomly with the vehicle distance meter. The photos on the following pages are typical of, but do not show all of the growth in the channel. Vegetation on both banks is dense and makes visual inspection difficult. Numerous downed trees and piles of debris in the channel should be removed and the channel should be cleared of vegetal growth before the next flood season. A major wash out area is located at end of Salt Creek road. This is being caused by some of the downed trees that should be removed to prevent further erosion. Little or no maintenance has been performed on this channel for the past several years. Tehama County needs to develop a maintenance program for this channel.

### SACRAMENTO RIVER AND TRIBUTARIES Salt Creek



Downstream from the end of Patterson Avenue. Bank vegetation is encroaching on the channel.



Upstream from the end of Patterson Avenue. Showing the dense vegetation in the channel.

### SACRAMENTO RIVER AND TRIBUTARIES Salt Creek



End of Salt Creek road, approximately 200 feet of erosion along left bank.



End of Salt Creek road, showing cause of washout and logs in channel.

### SACRAMENTO RIVER AND TRIBUTARIES Salt Creek



Upstream approximately 200 feet upstream from the confluence with the Sacramento river.



Logs and dense vegetation at the confluence with the Sacramento River.

#### SACRAMENTO RIVER AND TRIBUTARIES


**Maintained by City of Chico** 

#### **BIG CHICO CREEK**

On October 14, 2004, an inspection was made of the Big Chico Creek channel. The project channel begins at the Big Chico Creek Control Structure and extends 22.0 miles downstream to Big Chico Creek's confluence with the Sacramento River. Only 15 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all of the growth in the channel. Heavy amounts of vegetation exist along both banks of this channel. Vines extend across the channel at various locations. Little or no maintenance has been performed for the past several years. Thinning and removal of vegetation upstream of Manzanita Road and removal of snags on the right bank below the extension of Forest Avenue needs to be done before flood season.



Upstream from the bridge near Forest Avenue, heavy growth along both banks.



Downstream from the bridge near Forest Avenue, heavy growth along both banks.



Upstream from Highway 99, heavy growth along both banks.



Downstream from Highway 99, dense vegetation in channel.




Downstream from Esplanade, heavy growth on both banks.



Upstream from Chico State University, heavy growth on both banks.



Downstream from Highway 32, heavy growth on both banks.



Upstream Highway 32, tree blocking the channel.



Upstream at Rose, heavy growth and dense vegetation in the channel and along both banks.



Upstream at confluence and River Road bridge.

#### SACRAMENTO RIVER AND TRIBUTARIES


**Maintained by State of California** 

#### LINDO CHANNEL AND SANDY GULCH

On October 13, 2004, an inspection was made of Lindo Channel and Sandy Gulch. The project channel begins at the Lindo Channel Diversion Structure and extends downstream 13.0 miles to the channel's confluence with Big Chico Creek. Only 10.0 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all of the growth in the channel. Located by Mangrove on the right bank, there has been damage due to bikes or motorcycles. The portion of the channel from Manzanita Avenue to Big Chico Creek has heavy vegetation along both banks, but the channel is clear. Small growth in channel should be removed.



**Downstream from the Lindo Channel Diversion structure.** 



**Upstream from Manzanita Avenue.** 



Upstream from the bike path bridge at the extension of Madrone Avenue.



**Upstream at Mariposa.** 



Downstream from Mangrove, the channel and motorcycle damage on left bank.



Downstream from Mangrove, motorcycle damage on left bank.



**Downstream from Esplanade.** 



**Upstream from Nord Avenue, Highway 32.** 

### SACRAMENTO RIVER AND TRIBUTARIES Sandy Gulch



**Downstream from Oak Avenue.** 



**Upstream from Grape Way.** 

#### SACRAMENTO RIVER AND TRIBUTARIES

Maintained by the City of Chico

#### LITTLE CHICO CREEK

On October 12, 2005 an inspection was made of the Little Chico Creek channel. The project channel begins at the Little Chico Creek Control and Weir Structure and extends downstream for 18.0 miles to Alberton Road. Only 12.0 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all of the growth in the channel. Growth between the control structure and Lone Pine Avenue is moderate to heavy along both banks, but channel is clear. Selective thinning and fallen tree removal should be done prior to next flood season.



Downstream from the control structure, moderate growth in the channel.



**Downstream from Bruce Road.** 



**Downstream from Forest Avenue.** 



Downstream from Highway 99.



Upstream from Boucher Street. Dense growth on both banks.



Upstream from Mill Street. Dense growth on both banks.



**Downstream from Olive Street.** 



Upstream from Chestnut Street. Heavy overhead growth.



**Upstream from Crouch Avenue.** 



Upstream from Alberton Avenue. Scouring on left bank and in channel.

#### **CHAPTER II**

## PROJECT CHANNELS INSPECTED ON THE TRUCKEE RIVER AND THE FAIRFIELD VICINITY STREAMS

### PLACER COUNTY Maintained by Placer County

#### TRUCKEE RIVER

On November 2, 2004 an inspection was made of the Truckee River channel. The project channel begins at the Lake Tahoe Outlet Works and extends downstream for 0.6 mile. The entire 0.6-mile was inspected. The photos on the following pages are typical views of the channel. The channel is clear of vegetation growth and obstructions. Placer County has a good maintenance program.

#### PLACER COUNTY Truckee River



Upstream from Highway 89 toward the outlet structure.




**Downstream from Highway 89.** 

#### PLACER COUNTY Truckee River



Upstream from the bike bridge, 1,000 feet downstream of the Lake Tahoe outlet structure.



Downstream from the bike bridge.

#### PLACER COUNTY Truckee River



**Upstream from the Tahoe City lumber yard.** 



Downstream from the Tahoe City lumber yard, towards the downstream limits.

### SACRAMENTO RIVER AND TRIBUTARIES FAIRFIELD VACINITY STREAMS

**Maintained by Fairfield-Suisun Sewer District** 

#### McCOY CREEK

On October 29, 2004 an inspection was made of the McCoy Creek channel. The project channel begins at Prosperity Lane and extends downstream 1.22 miles to McCoy Creeks' confluence with Buffer Channel. The entire 1.22 miles were inspected. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. Vegetation is minimal and should not affect the flow. The patrol roads should be sterilized prior to flood season. The maintaining agency has an excellent maintenance program.

# SACRAMENTO RIVER AND TRIBUTARIES FAIRFIELD VACINITY STREAMS McCoy Creek



**Downstream from Bella Vista Drive.** 



**Downstream from Emperor Drive.** 

# SACRAMENTO RIVER AND TRIBUTARIES FAIRFIELD VACINITY STREAMS McCoy Creek



**Upstream from Pintail Avenue.** 



**Upstream from Anderson Drive.** 

### SACRAMENTO RIVER AND TRIBUTARIES FAIRFIELD VACINITY STREAMS

**Maintained by Fairfield-Suisun Sewer District** 

#### LAUREL CREEK

On October 29, 1004 an inspection was made of the Laurel Creek Channel. The project channel begins at Gulf Drive and extends downstream 2.78 miles to Laurel Creek's confluence with McCoy Creek. The entire 2.78 miles were inspected. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. Vegetation is minimal in the channel and does not affect the flow, however, new growth should be removed or sprayed. The maintaining agency has an excellent maintenance program.

# SACRAMENTO RIVER AND TRIBUTARIES FAIRFIELD VACINITY STREAMS Laurel Creek



**Upstream from Cement Hill Road towards Gulf Drive.** 



**Downstream from Cement Hill Road.** 

#### SACRAMENTO RIVER AND TRIBUTARIES FAIRFIELD VACINITY STREAMS Laurel Creek



**Downstream from Meadowlark Drive.** 



**Downstream from Blossom Road.** 

# SACRAMENTO RIVER AND TRIBUTARIES FAIRFIELD VACINITY STREAMS Laurel Creek



Downstream from Matthew Road towards Railroad culvert under crossing.



Downstream from Worley Road towards the confluence with McCoy Creek.

### SACRAMENTO RIVER AND TRIBUTARIES FAIRFIELD VACINITY STREAMS

**Maintained by Fairfield-Suisun Sewer District** 

#### UNION AVENUE DIVERSION

On October 29, 2004, an inspection was made of the Union Avenue Diversion Channel. The project channel begins at North Texas Street and extends downstream 0.73 mile to Gulf Drive. The entire 0.73-mile was inspected. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. Vegetation is minimal in the channel and does not affect the flow, however, new growth should be removed or sprayed. The maintaining agency has an excellent maintenance program.

### SACRAMENTO RIVER AND TRIBUTARIES FAIRFIELD VACINITY STREAMS

**Union Avenue Diversion** 



**Downstream from North Texas Street.** 



**Downstream from Camrose Avenue.** 

### SACRAMENTO RIVER AND TRIBUTARIES FAIRFIELD VACINITY STREAMS

**Union Avenue Diversion** 



**Downstream from Dover Avenue.** 



**Upstream from the downstream limits at Gulf Drive.** 

#### **CHAPTER III**

## PROJECT CHANNELS INSPECTED ON THE SAN JOAQUIN RIVER AND TRIBUTARIES

**Maintained by the Merced Irrigation District for Merced County** 

#### **BEAR CREEK**

On November 2, 2004 an inspection was made of Bear Creek. The project channel begins 2.0 miles upstream of the confluence with Burns Creek and extends downstream 21.0 miles to Bert Crane Road. Only 15 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show, all the growth in the channel. Moderate to heavy growth exists along both banks from the confluence with Burns Creek to approximately the Merced City limits. From Franklin Road to Dickerson Ferry Road, the channel and banks are overgrown to the extent that moderate flows could be adversely affected causing bank overflow. A clearing program should be implemented immediately. However, The California Department of Fish and Game has stopped the channel-clearing program. Both agencies are working to resolve the issues and continue channel maintenance.



Downstream of the Bonner Road bridge.




**Downstream from Arboleda Drive.** 



Upstream from Kirby Road.



Bank washing away downstream from Kirby Road.



**Downstream from McKee Road.** 



**Upstream from "R" Street.** 



**Upstream from "16" Street.** 



Downstream from Highway 99.



**Downstream from Franklin Road.** 



Downstream from Highway 140.



**Upstream from Gurr Road.** 



**Upstream from Dickenson Ferry Road.** 

**Maintained by the Merced Irrigation District for Merced County** 

#### **BLACK RASCAL CREEK**

On November 4, 2004 an inspection was made of Black Rascal Creek Channel. The project channel begins at Crocker Dam and extends downstream 6.5 miles to Black Rascal Creek's confluence with Bear Creek. Only 2.8 miles could be inspected. Views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. The wild growth should be cleared to allow proper design flow. However, the California Department of Fish and Game has stopped the channel-clearing program. Both agencies are working to resolve the issues and continue channel maintenance.

**Black Rascal Creek** 



**Downstream from the Crocker Dam.** 



**Downstream from Franklin Road.** 

**Black Rascal Creek** 



**Downstream from Gurr Road.** 



**Upstream from Highway 140.** 

**Black Rascal Creek** 



**Downstream from Quinley Avenue.** 



**Downstream from Oak Avenue.** 

Maintained by Merced Irrigation District for Merced County

#### **BURNS CREEK**

On November 3, 2004 an inspection was made of Burns Creek. The project channel begins 2.0 miles upstream of Burns Creek's confluence with Bear Creek and extends 2.0 miles downstream to the confluence. Only 1.0 mile of channel could be inspected due to inaccessibility. The photos on the following pages are typical of, but do not show all the growth in the channel. There appears to have been little maintenance performed in the past years. Merced County should mechanically clear and spray the channel. However, the California Department of Fish and Game has stopped the channel-clearing program. Both agencies are working to resolve the issues and continue channel maintenance.



**Downstream from Bonner Road.** 




Upstream from the low water crossing.


**Maintained by the Merced Irrigation District for Merced County** 

### MARIPOSA CREEK/DUCK SLOUGH


On November 3, 2004 an inspection was made of Mariposa Creek/Duck Slough channel. The project channel begins 4.0 miles upstream of Fresno Road, and extends downstream for 16.5 miles to Highway 59. Only 6.2 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. The wild growth should be cleared to allow proper design flow. However, the California Department of Fish and Game has stopped the channel-clearing program. Both agencies are working to resolve the issues and continue channel maintenance.



Downstream from White Rock Road.



**Downstream from Fresno Road.** 



**Downstream from Santa Fe Avenue.** 



**Upstream from Burchell Avenue.** 



Downstream from Plainsburg Road.



**Downstream from Whealan Road.** 



**Downstream from Healy Road.** 



**Upstream from Highway 59.** 

**Maintained by the Merced Irrigation District for Merced County** 

#### MILES CREEK

On November 4, 2004 an inspection was made of Miles Creek channel. The project channel begins 1.5 miles upstream of Childs Avenue and extends downstream for 12.0 miles to Highway 59. Only 5.6 miles of the channel could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. There is intermittent heavy brush growth with garbage backed up against the growth throughout the system. The channel is constricted by trees and brush from Riley Road to the Miles Creek Dam and should be cleared before next flood season. However, the California Department of Fish and Game has stopped the channel-clearing program. Both agencies are working to resolve the issues and continue channel maintenance.



**Upstream from Childs Avenue.** 




**Downstream from Santa Fe Avenue.** 



Downstream from Plainsburg Road.



**Downstream from Gerard Avenue.** 



**Downstream from Whealan Road** 



Downstream from Arboleda Drive. Notice the blackberrys on the right bank.



**Downstream from Miles Road.** 



**Downstream from Healy Road.** 



**Downstream from Tyler Road.** 



Upstream from Highway 59.
The channel is overgrown with wild growth.

**Maintained by the Merced Irrigation District for Merced County** 

### **OWENS CREEK**

On November 5, 2004 an inspection was made of Owens Creek channel. The project channel begins at Cunningham Road and extends downstream for 2.0 miles to Owens Creek Diversion channel. Only 1.2 miles of the channel could be inspected due to limited access. Major tule growth was found in the channel. Tules should be sprayed to control growth. However, the California Department of Fish and Game has stopped the channel-clearing program. Both agencies are working to resolve the issues and continue channel maintenance.



**Downstream from Cunningham Road.** 



Upstream from Childs Avenue.
Note the tule growth.



**Upstream from the extension of Mission Avenue.** 

Maintained by the Madera County Flood Control and Water Conservation Agency

#### **ASH SLOUGH**

On November 16, 2004 an inspection was made Ash Slough channel. The project channel begins at the Ash and Berenda Slough Bifurcation Structure and extends downstream for 19.0 miles to Avenue 22. Only 10.3 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. There are some willows and bamboo on the banks, but the channel appears to be in satisfactory condition. There has been no apparent maintenance in recent years. The new growth needs to be removed and sprayed.



**Downstream from Ash Slough bifurcation structure.** 



**Upstream from Santa Fe Drive.** 



**Upstream from Road 19.** 



**Upstream from Road 13.** 



**Upstream from Avenue 25.** 



Upstream from Avenue 231/2.



**Downstream from Highway 152** 



**Upstream from Road 9.** 

Maintained by the Madera County Flood Control and Water Conservation Agency

#### **BERENDA SLOUGH**

On November 17, 2004 an inspection was made of Berenda Slough channel. The project channel begins at the Ash and Berenda Slough Bifurcation Structure and extends downstream for 18.5 miles. Only 13.0 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. Dense wild growth is chocking the channel 200 yards from the structure. The channel has areas of willow and bamboo growth that should be cleared. There appears to have been little to no maintenance performed in the past several years. The wild growth should be cleared to allow proper design flow.



Downstream from the Berenda Slough bifurcation structure.



**Upstream from Santa Fe Drive.** 



**Upstream from Avenue 26.** 



Downstream from Road 19.



Downstream from 22½ Avenue low water crossing.



Downstream Road 14.



Upstream from Avenue 20. Trees and wild growth in channel.



**Upstream Avenue 20.** 

#### SAN JOAQUIN RIVER AND TRIBUTARIES

Maintained by the Madera County Flood Control and Water Conservation Agency

### **CHOWCHILLA RIVER**

On November 18, 2004 an inspection was made of the Chowchilla River channel. The project channel begins at Buchanan Dam and extends downstream for 28.5 miles to Schultz Road. Only 18.4 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. The channel east of Highway 99 is through pastureland with trees immediately upstream of Road 19 (White Rock Road) posing the only constriction. From Highway 99 downstream there are areas of heavy brush and tree growth that should be cleared. Upstream from Avenue 26, wild growth has been partially removed about 100 feet away from bridge. Downstream from Avenue 26, the channel is cleared by livestock grazing. Where there is livestock grazing, fences have been put up across the channel and other obstructions placed in the channel and along the banks. These areas should be cleared to allow the water to flow without collecting debris. Down from Avenue 25, garbage needs to be removed from the channel. The wild growth should be cleared to allow proper design flow.



Downstream from Buchanan Dam.




One mile downstream from Buchanan Dam.



**Downstream from Santa Fe Drive.** 



**Upstream from White Rock Road.** 



Downstream from Road 15 (Minturn Road).



Downstream low water crossing Road 27.



Downstream Road 13 (Vista Avenue).



Upstream Road 11. Fencing across the channel.



**Downstream from Road 9 (Bliss Road)** 



**Upstream of Avenue 25 (Washington Road).** 



Downstream from Avenue 25, showing garbage in channel.



**Upstream from Schultz Road.** 

Maintained by the Madera County Flood Control and Water Conservation Agency

### **FRESNO RIVER**

On November 18, 2004 an inspection was made of the Fresno River channel. The project channel begins at Hidden Dam and extends downstream for 13.0 miles to Road 18½. Only 9.0 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. There is some small willow growth in the channel but the maintaining agency does a good job of discing it annually so that the growth is kept under control. The District has an excellent maintenance program.

## SAN JOAQUIN RIVER AND TRIBUTARIES Fresno River



Downstream from Road 603 below Hidden Dam.



**Downstream from Cleveland Avenue.** 

## SAN JOAQUIN RIVER AND TRIBUTARIES Fresno River



Downstream from "D" street, looking at the Gateway bridge.



Downstream from Road 23.

## SAN JOAQUIN RIVER AND TRIBUTARIES Fresno River



Downstream from Road 20.
Bamboo and small trees growing in the channel.



Upstream from the downstream boundary.

Maintained by the San Joaquin County Flood Control District

### NORTH LITTLEJOHN CREEK

On November 29, 2004 an inspection was made of the North Littlejohn Creek channel. The project channel begins at its bifurcation with South Littlejohn Creek and extends downstream for 18.0 miles to North Littlejohn Creek's confluence with French Camp Slough. Only about 12.5 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. There are areas, especially at the upper end, that have moderate tree growth in and around the channel. Wild growth in channel should be cleared.

# SAN JOAQUIN RIVER AND TRIBUTARIES North Littlejohn Creek



Upstream at the bifurcation of North Littlejohn Creek and South Littlejohn Creek.



Structure at Hewit Lane.

## SAN JOAQUIN RIVER AND TRIBUTARIES North Littlejohn Creek



Downstream from Van Allen Road, dense vegetation in channel.



**Upstream from Mariposa Road.** 

Maintained by the San Joaquin County Flood Control District

### **DUCK CREEK DIVERSION CHANNEL**

On November 30, 2004 an inspection was made of the Duck Creek Diversion channel. The project channel begins at the Duck Creek Diversion Weir and Control Structure and extends downstream for 5,000 feet to its confluence with South Littlejohn Creek. All 5,000 feet were inspected. The views of the channel are primarily at road crossings. The channel is clear of any growth, there is a pipe exposed on the right bank, upstream from Highway 4. The District has a good maintenance program.

## SAN JOAQUIN RIVER AND TRIBUTARIES Duck Creek Diversion Channel



Downstream from the diversion structure.



Exposed pipe on the right bank, upstream from Highway 4.

## SAN JOAQUIN RIVER AND TRIBUTARIES Duck Creek Diversion Channel



Downstream from Highway 4.



Confluence of Duck Creek and Littlejohn Creek.

Maintained by the San Joaquin County Flood Control District

### SOUTH LITTLEJOHN CREEK

On November 30, 2004 an inspection was made of the South Littlejohn Creek channel. The project channel begins at Farmington Dam and extends downstream for 21.7 miles to South Littlejohn Creek's confluence with Lone Tree Creek. Only about 12.5 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. The channel is clear, but from Jack Tone Rd. to Hwy. 99 there are large amounts of water grass in certain areas. Water grass should be sprayed.

# SAN JOAQUIN RIVER AND TRIBUTARIES South Littlejohn Creek



**Downstream from the confluence with Duck Creek.** 




**Downstream from Stanley Road.** 

# SAN JOAQUIN RIVER AND TRIBUTARIES South Littlejohn Creek



Downstream from Van Allen Road.



**Downstream from Mariposa Road.** 

# SAN JOAQUIN RIVER AND TRIBUTARIES South Littlejohn Creek



**Upstream from Jack Tone Road.** 



**Upstream from Austin Road.** 

Maintained by the San Joaquin County Flood Control District

### SOUTH LITTLEJOHN CREEK, NORTH BRANCH

On November 29, 2004 an inspection was made of the South Littlejohn Creek channel. The project channel begins at Farmington Dam and extends downstream for 21.7 miles to South Littlejohn Creek's confluence with Lone Tree Creek. Only about 17.0 miles could be inspected due to limited access. The views of the channel are primarily at road crossings. The photos on the following pages are typical of, but do not show all the growth in the channel. The channel is clear, but from Jack Tone Rd. to Hwy. 99 there are large amounts of water grass in certain areas. Water grass should be sprayed.

### SAN JOAQUIN RIVER AND TRIBUTARIES South Littlejohn Creek – North Branch



Downstream from the North and South Littlejohn split.



**Upstream Jack Tone Road.** 

### SAN JOAQUIN RIVER AND TRIBUTARIES South Littlejohn Creek – North Branch



**Upstream from Austin Road.** 

### **CHANNEL INDEX**

Inspection Date	Maintaining	Channel & Flow Capacity	Remarks	Action	Page
	Agency Adin Community	Ash Creek			raye
10/22/04	Service District	ASN Creek	Excellent Maintenance Program	No action needed at this time.	6
10/22/04	Adin Community	Dry Creek	Moderate to heavy willow	Remove or spray willow	
	Service District		growth in channel		10
10/15/04	Tehama County	McClure Creek	Satisfactory Maintenance	No action needed at this time.	
			Program		14
10/15/04	Tehama County	Salt Creek	Poor Maintenance Dense	Develop a Maintenance	
			Vegetation	Program	18
10/14/04	City of Chico	Big Chico Creek	Dense Vegetation along	Control wild growth	
		(17,500 cfs)	banks		22
10/13/04	Department of	Lindo Channel	Small wild growth in	Control wild growth	
	Water Resources	(14,500 cfs)	channel		28
10/13/01	Department of	Sandy Gulch	Dense wild growth along	Control wild growth	
	Water Resources	(6,000 cfs)	banks		33
10/12/04	City of Chico	Little Chico Creek	Dense to moderate wild	Selective thinning and fallen	
		(13,000 cfs)	growth	trees removed	34
11/2/04	Placer County	Truckee River	Clear Channel	No action needed at this time	
		(6,000 cfs)			42
10/29/04	Fairfield Sewer	McCoy Creek	Clear Channel	Excellent Maintenance	
	District	(2,000 cfs)		Program	46
10/29/04	Fairfield Sewer	Laurel Creek	Minimal vegetation	Remove small growth	
	District	(3,700 cfs)			50
10/29/04	Fairfield Sewer	Union Avenue Diversion	Minimal vegetation	Remove small growth	
	District	(2,600 cfs)			54
11/2/04	Merced Irrigation	Bear Creek	Moderate to heavy wild	A clearing program should be	
	District	(3,700 cfs)	growth	implemented	58
11/4/04	Merced Irrigation	Black Rascal Creek	Moderate wild growth	Control wild growth	
	District	(3,900 cfs)			66
11/3/04	Merced Irrigation	Burns Creek	Little maintenance	District should clear &	
	District.	(2,000 cfs)	performed	maintenance spray channel	70
11/3/04	Merced Irrigation	Mariposa Creek	Moderate wild growth in	Clear to allow proper design	
	District	(2,250 cfs)	channel	flow	72
11/4/04	Merced Irrigation	Miles Creek	Intermittent dense brush	District should clear &	
	District	(1,000 cfs)	growth throughout the	maintenance spray channel	
			system		78
11/5/04	Merced Irrigation	Owens Creek	Minor tule growth	Tule should be sprayed	
	District	(400 cfs)			84
11/16/04	Madera County	Ash Slough	Minor willow & bamboo in	Remove new growth	
		(31,000 cfs)	channel		88
11/17/04	Madera County	Berenda Slough	Dense wild growth in	Remove wild growth	
		(6,000 cfs)	channel		94
11/18/04	Madera County	Chowchilla River	Dense brush downstream	Clear brush	
		(21,575 cfs)	of Hwy 99		100
11/18/04	Madera County	Fresno River	Small willow new growth	Control new growth	
		(23,000 cfs)	g	g. c	108
11/29/04	San Joaquin Flood	N. Littlejohn Creek	Moderate tree growth	Control growth	
	Control District	(8,000 cfs)		<b>3</b>	112
11/30/04		Duck Creek Diversion	Clear Channel	Good Maintenance Program	
. 1,00,04	Control District	Channel (250 cfs)	J.Jul Gildillioi		440
44/20/04			Woter and an decimant	Corey water areas	116
11/30/04	-	South Littlejohn Creek	Water grass downstream	Spray water grass	
	Control District	(8,000 cfs)	of Hwy. 99		120
11/29/04	San Joaquin Flood	South Littlejohn Creek	The channel is overall	No action needed at this time	
	Control District	North (16,000 cfs)	clear		124
	1	<u>-</u>	I .		

127 2004 CHANNEL REPORT